



## Contamination

---

Contamination refers to the inclusion of paint of another color, which becomes visible as patches.

### Q1:

**Is dust falling on the substrates during transportation?**

### A1:

Check the substrates and remove dust.

Wipe them with a cloth before coating.

### Q2:

**Is the color change process adequate?**

### A2:

Clean the paint tank, paint booth, hose, and spray gun more thoroughly.

Replace the powder with a fresh one.

### Q3:

**Is there any adverse effect of the pretreatment?**

### A3:

Check the condition of the substrate before coating.