



Nonuniform treatment

Pretreatment finished in a nonuniform manner accordingly causes an uneven thickness of the deposited film.

Q1:

Uneven drying in pretreatment process

A1:

Install a spray device to prevent drying-up.

Q2:

Uneven degreasing and other defects in pretreatment

A2:

- Check whether there was any oil type or oil consumption change.
- Keep the bath under proper control.
- With respect to paint, it is possible to mitigate the effect of nonuniform treatment by increasing the film's electrical resistance (with a higher ash content and lower solvent).