Troubleshooting

Solvent Paints

Lifting



Lifting refers to the condition that the previously coated paint film softens and develops wrinkles, which occurs when recoating paint/coating over a dry paint film.

Q1:

Did you achieve a thick paint film in a single coating operation?

A1:

Recoat the substrate thinly and repeatedly.

Q2:

Is the amount of the thinner used for dilution larger than appropriate?

A2:

Use an appropriate dilution condition for coating.

Q3:

Is the solubility of the thinner used for the recoating paint higher than appropriate?

A3:

Use an appropriate thinner.

Q4:

Is the recoating paint appropriate?

A4:

Adhere strictly to the appropriate coating specifications.

Q5:

Did you perform recoating in a time when it is prohibited?

A5:

Avoid a time when recoating is prohibited.