



Yellowing refers to a paint film surface being more yellowish than the standard panel. Alternatively, it is a high  $\Delta b$  value in terms of color difference.

#### Q1:

**Did overbaking occur?**

#### A1:

Measure the oven temperature.

Correct the time, temperature, and temperature rising curve appropriately.

Adjust the airflow opening.

#### Q2:

**Is fresh air sufficient in the oven?**

#### A2:

Ensure appropriate air conditions in the oven.

Inspect the filter at the air intake port for dirt. Replace the filter.

#### Q3:

**Has the NO<sub>x</sub> level increased in the oven?**

#### A3:

Check the NO<sub>x</sub> level with a simple gas detector. Raise the ventilation rate.